

Projects Recommended to be Removed

1000 - 1999: Public Suggested Projects
2000 - 2999: New Identified Projects
U000 - U999: Previously Planned Projects

Legend

○	Does not support goal.
◐	Somewhat supports goal.
●	Definitely supports goal.

TAC: Technical Advisory Committee
GAPS: Geographic Area Projects
VOH: Virtual Open House

TSP Update ID	Geographic Sub Area	Project Name / Street Name	Segment / Locations	Project Description	Addresses a Gap?	Addresses a Deficiency?	TSP Goal Assessment of Project						Comment	Reason for Removal
							Goal 1: Sustainable	Goal 2: Local Businesses and Jobs	Goal 3: Liveable and Local	Goal 4: Safety and Health	Goal 5: Equity	Goal 6: Fiscally Responsible		
1008	SW	OR 213	OR 213 / Union Mills Rd intersection	Install signal to replace existing stop-controlled intersection	No	No	◐	◐	◐	◐	◐	○		Does not address gap or deficiency
1013	SW	Stafford Rd	65th Ave / Stafford Rd intersection	Construct roundabout to replace existing T-intersection	No	Yes	●	◐	●	●	◐	◐	GAPS #2: Combine with U180	Duplicate to U180
1019	CRCIA	OR 213	I-205/ OR 213 interchange	Extend bikeway	Yes	No	●	◐	●	●	●	◐	TAC #5: Keep in, proposal to complete I-205 multi-use path in Sunrise Project Final Environmental Impact Statement	Duplicate to U904
1025	SW	OR 213	OR 213 / Union Mills Rd intersection	Install right-turn lane on Union Mills Rd	No	No	◐	◐	◐	◐	◐	○		Does not address gap or deficiency
1033	M	Thiessen Rd	Thiessen Rd / Aldercrest Rd intersection	Install eastbound left turn lane and westbound right turn lane	No	Yes	◐	◐	●	●	◐	◐		Duplicate to 2113
1035	M	Jennings Ave	River Rd to OR 99E	Provide sidewalks and bike lanes along segment	Yes	No	●	◐	●	●	●	●	GAPS #2: References U806, which isn't on the list	Duplicate to U149
1036	M	Oatfield Rd	Park Ave to Lake Rd	Close section of roadway to through traffic.	No	No	◐	○	◐	●	○	◐	GAPS #2: Agree with removal	Does not address gap or deficiency
1046	M	Roethe Rd	River Rd and Byron Rd	Determine appropriate traffic calming strategies	Yes	No	●	◐	●	●	●	◐		Duplicate to U818
1052	SW	Rail line	Canby to Molalla	Rehabilitate existing rail lines to off-road multi-use trail to accommodate bike, ped, and equestrian use	Yes	No	●	◐	●	●	●	◐	TAC #5 Duplicate to U784 VOH: The rail line has the potential to be a wonderful paved trail between Canby & Molalla	Duplicate to U784
1056	SW	Cliffside Dr	Cliffside Dr	Pave Cliffside Dr	No	No	◐	○	◐	◐	◐	○		Does not address gap or deficiency
1063	NW	Willamette River	Between cities of Oregon City and Newberg	Construct bridge	Yes	Yes	●	●	●	●	●	◐		Duplicate to U925
2024	CRCIA	Evelyn St	SE Jennifer St to OR 212	Add bikeways	Yes	No	●	●	●	●	●	◐		Duplicate to U796
2025	CRCIA	106th Ave	SE Jennifer St to OR 212	Add bikeways	Yes	No	●	●	●	●	●	◐		Duplicate to U785
U142	M	Oatfield Rd	Oatfield Rd / Courtney Rd intersection	Install traffic signal	No	No	○	◐	◐	○	◐	○	TAC #5: Agree to remove, candidate road safety audit corridor will address safety concerns. GAPS #2: Need to have intersection sight distance reviewed and consider left-turn lane	Intersection addressed by 2088
U148	M	Thiessen Rd	Thiessen Rd / Hill Rd intersection	Widen, add left-turn lane on Thiessen Road	No	Yes, but fails	◐	○	◐	○	◐	○	TAC #5: Consider two-way stop controlled or roundabout GAPS #2: Overlaps with 2112?	Intersection addressed by 2112
U182	SW	Forsythe Rd	Railroad crossing between Clackamas River Dr and boardwalk	Upgrade railroad crossing	No	No	○	○	○	○	○	○		Does not address gap or deficiency
U200	SW	Ferguson Rd	Redland Rd to Maplelane Rd	Remove or decrease horizontal curve along Redland Rd, relocate intersection, install eastbound right-turn lanes and westbound left-turn lanes	No	No	◐	○	◐	●	◐	◐		Does not address gap or deficiency
U252	SW	Springwater Rd	Springwater Rd / Redland Rd intersection	Install northbound left-turn lane	No	No	◐	○	◐	◐	◐	○		Does not address gap or deficiency
U253	E	Springwater Rd	Springwater / Hayden Rd intersection	Install southbound left-turn lane	No	No	◐	○	◐	●	◐	◐		Does not address gap or deficiency
U274	SW	Denbrook Rd	Railroad crossing west of Boones Ferry Rd	Upgrade railroad crossing	No	No	○	○	○	◐	○	○		Does not address gap or deficiency
U301	SW	Oak Grove Rd	Railroad crossing southwest of Macksburg Rd	Construct new railroad crossing	No	No	○	○	○	○	○	○		Does not address gap or deficiency
U307	SW	Sconce Rd	Bridge	Reconstruct and widen to 32 feet	No	No	○	○	○	◐	○	○		Does not address gap or deficiency
U312	SW	Vick Rd	Molalla Ave to OR 213	Widen to rural local standard	No	No	◐	○	◐	●	◐	◐		Does not address gap or deficiency

Projects Recommended to be Removed

1000 - 1999: Public Suggested Projects
2000 - 2999: New Identified Projects
U000 - U999: Previously Planned Projects

Legend	
○	Does not support goal.
◐	Somewhat supports goal.
●	Definitely supports goal.

TAC: Technical Advisory Committee
GAPS: Geographic Area Projects
VOH: Virtual Open House

TSP Update ID	Geographic Sub Area	Project Name / Street Name	Segment / Locations	Project Description	Addresses a Gap?	Addresses a Deficiency?	TSP Goal Assessment of Project						Comment	Reason for Removal
							Goal 1: Sustainable	Goal 2: Local Businesses and Jobs	Goal 3: Liveable and Local	Goal 4: Safety and Health	Goal 5: Equity	Goal 6: Fiscally Responsible		
U313	SW	Vick Rd	Railroad crossing between Molalla Ave and Appaloosa Dr	Construct new railroad crossing	No	No	○	○	○	○	○	○		Does not address gap or deficiency
U324	SW	Groshong Rd	Blair Rd to Bird Rd	Widen to rural minor arterial standard with shoulders / bikeways and turn lanes at major intersections	No	No	●	○	●	●	●	○		Does not address gap or deficiency
U429	E	US 26	US 26 / OR 173 intersection	Remove or decrease horizontal and vertical curves	No	No	◐	○	●	●	●	◐	TAC #5: Remove	Duplicate to U532 and 2068
U430	SW	OR 211	Meridian Rd / OR 211 intersection	Construct eastbound and westbound right-turn lanes and eastbound left-turn lane	No	No	◐	○	◐	◐	◐	○		Does not address gap or deficiency
U432	SW	OR 211	Wright Rd / OR 211 intersection	Install eastbound right-turn lane	No	No	◐	○	◐	◐	◐	○		Does not address gap or deficiency
U433	SW	OR 211	Schieffer Rd / OR 211 intersection	Install eastbound right-turn lane	No	No	◐	○	◐	◐	◐	○		Does not address gap or deficiency
U434	E	OR 211	Hayden Rd / OR 211 intersection	Add westbound right-turn lane	No	No	○	◐	◐	◐	◐	○	TAC #5:TAC agreement for consider removing, low volumes	Does not address gap or deficiency
U435	E	OR 211	Eagle Creek Rd / OR 211 intersection	Add eastbound right-turn lane	No	No	○	◐	◐	◐	◐	○	TAC #5: low volumes	Does not address gap or deficiency
U436	E	OR 211	367th Ave / OR 211 intersection	Add eastbound right-turn lane	No	No	○	◐	◐	◐	◐	○	TAC #5: low volumes	Does not address gap or deficiency
U447	SW	OR 99E	New Era Rd / OR 99E intersection	Install northbound right-turn lane	No	Analysis Needed	◐	◐	◐	◐	◐	◐		Intersection addressed by 2081
U448	SW	OR 99E	Lone Elder Rd / OR 99E intersection	Install north bound right-turn lane	No	Analysis Needed	◐	◐	◐	◐	◐	◐		Intersection addressed by 2080
U453	E	US 26	US 26 / Orient Dr	Add westbound right-turn lane	No	No	○	◐	◐	◐	◐	○	TAC #5 :On ODOT Safety Audit Corridor GAPS #2: Already has westbound right turn lane?	Does not address gap or deficiency
U455	E	US 26	US 26 / East Fernwood Circle	Add westbound left-turn lane	No	No	○	◐	◐	◐	◐	○	TAC #5: low volumes and on Safety Audit Corridor	Does not address gap or deficiency
U477	SW	Beavercreek Rd	Oregon City limits to Henrici Rd	Widen to 5 lanes	No	No	○	○	◐	◐	○	○		Does not address gap or deficiency
U528	E	OR 173	Timberline Lodge to US 26	Add pull-offs; identify other safety improvements	No	No	◐	○	◐	●	●	○	GAPS #2: Map missing removal hatching	Does not address gap or deficiency
U530	SW	OR 211	Mathias Rd to Wright Rd	Add passing lanes	No	No	○	○	◐	◐	○	◐		Does not address gap or deficiency
U540	SW	OR 213	Molalla Ave to Toliver Rd	Add passing lanes to mile post 15.34	No	No	○	○	◐	◐	○	○		Does not address gap or deficiency
U542	SW	OR 213	Molalla Ave/Clack. Comm. College to Leland Rd.	Access management, widen to 4 lanes with left turn lanes	No	No	○	○	◐	◐	○	○		Does not address gap or deficiency