TECHNICAL MEMORANDUM Lake County & City of Paisley TSP Update

Final Future Conditions and Needs

Date: September 21, 2015

Rick DuMilieu, Lake County

From: Matt Kittelson, PE

cc: Devin Hearing, ODOT Region 4

The purpose of this memorandum is to document the future (2035) traffic conditions for the Lake County and City of Paisley TSP updates. In addition, this memorandum documents future need based on expected future conditions and identified deficiencies within existing conditions.

Project #: 18547

BACKGROUND

To:

The Lake County and City of Paisley TSP updates have been ongoing since April 2015. Since that time, efforts have been focused on establishing project goals and objectives, documenting existing plans and policies, conducting an existing conditions inventory, and identifying existing deficiencies. Existing deficiencies were identified through technical evaluation, project team input, and via a public outreach effort conducted during July 2015.

DEVELOPMENT OF YEAR 2035 TRAFFIC FORECASTS

Traffic Forecast Projections

Future (2035) traffic volumes were developed using Oregon Department of Transportation's (ODOT's) historical trends method, which relies on historic traffic volumes to develop an annual growth rate. ODOT maintains Future Volumes Tables that summarize current and future year traffic volumes for state roadways. Based on guidance from ODOT's Analysis Procedure Manual (APM), the projected average annual growth is 0.25 percent for all Lake County & City of Paisley roadways (Reference 1). The same growth rate was used on state and county roadways.

The Methodology Memo, which is included as Appendix A, provides the traffic volumes projections for the locations that were used to develop the growth rate.

FUTURE TRAFFIC CONDITIONS AND NEEDS

The forecast 2035 traffic operations are summarized in the following sections. The technical analysis of the forecast 2035 transportation system is based on ADT for roadway segments and 30th highest hour traffic volume forecasts for intersections.

Year 2035 Forecast Traffic Volumes

The projected 0.25 percent annual growth rate was applied to existing 2014 volumes to estimate forecast year 2035 traffic volumes.

Year 2035 Forecast Intersection Operations

Forecast 2035 transportation system capacity analysis was conducted based on forecast traffic volumes. The operational results indicate that no operational improvements are needed to meet State, County, or City operational standards for each respective facility in 2035.

The future conditions operational analysis was conducted based on the peak 15-minute period of traffic flow at each study intersection. No changes to the existing lane configurations and traffic control devices were incorporated in this analysis because there are no planned improvements at the intersections.


Figure 1 summarizes the 2035 30th highest hour traffic volumes and the resulting intersection operations. All study intersections are expected to operate with volume-to-capacity (v/c) ratio of less than 0.1. All intersections are expected to meet their performance standards in 2035. *Appendix B includes the operational analysis worksheets for all study intersections*.


Kittelson & Associates, Inc. Bend, Oregon

Lane Configurations and Traffic Control Devices


Existing Traffic Volumes - PM Peak Hour


Highway 395 and Highway 140





Highway 31 and Highway 395





Future Conditions Lake County, OR Figure **1**

FUTURE NEEDS

Based on the assessment of existing and future conditions, Table 1 documents future transportation needs within the County and City.

Table 1. Future Transportation Needs in Lake County

Fixed-object and non-collision crashes OR 31 from Deschutes County to Fort Rock Road Safety OR 31 along Summer Lake Safety US 395 / OR 31 OR 140 from Plush Cutoff Road to Plush-Adel Road Safety Christmas Valley Safety Christmas Valley Safety OR 140 ~10 miles west of Safety OR 140 ~210 miles west of Safety OR 140 ~210 miles west of Safety OII Dri Road (5-14G) Active Sidewalks to Paisley Limited sidewalks exist Limited sidewalks exist High frequency of fixed-object crashes. Wind and speed object crashes. Wind and speed are common contributing factor to crashes. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. High frequency of fixed-object crashes. Wind and speed are common contributing factor to crashes. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. High frequency of fixed-object crashes. Wind and speed are common contributing factor to crashes. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. County officials and residents believe these turns have a high potential for crashes. Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Steep grade east of Christmas Valley. Currently posted at 8%. Limited sidewalks exist Limited recreational biking routes exist. Potential	Category	Name	Description
Safety collision crashes crashes. This includes collisions with animals. OR 31 from Deschutes County to Fort Rock Road object crashes, More passing lanes may be needed. High frequency of fixed-object crashes. Wind and speed are common contributing factor to crashes. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. OR 140 from Plush Cutofff Road to Plush-Adel Road observed data. Road winds through canyon. Fort Rock Road to Christmas Valley "S" turns. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. High frequency of fixed-object crashes. Wind and speed are common contributing factor to crashes. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. High frequency of fixed-object crashes. Wind and speed are common contributing factor to crashes. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. County officials and residents believe these turns have a high potential for crashes. Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Steep grade east of Christmas Valley. Currently posted at 8%. OR 140 ~10 miles west of Nevada border Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Active Sidewalks to Paisley School in Paisley Limited sidewalks exist Limited sidewalks exist	3 /		·
Safety collision crashes crashes. This includes collisions with animals. OR 31 from Deschutes County to Fort Rock Road object crashes, More passing lanes may be needed. High frequency of fixed-object crashes. Wind and speed are common contributing factor to crashes. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. OR 140 from Plush Cutofff Road to Plush-Adel Road observed data. Road winds through canyon. Fort Rock Road to Christmas Valley "S" turns. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. High frequency of fixed-object crashes. Wind and speed are common contributing factor to crashes. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. High frequency of fixed-object crashes. Wind and speed are common contributing factor to crashes. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. County officials and residents believe these turns have a high potential for crashes. Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Steep grade east of Christmas Valley. Currently posted at 8%. OR 140 ~10 miles west of Nevada border Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Active Sidewalks to Paisley School in Paisley Limited sidewalks exist Limited sidewalks exist		Fixed-object and non-	High frequency of fixed-object and non-collision
Safety County to Fort Rock Road object crashes. More passing lanes may be needed. High frequency of fixed-object crashes. Wind and speed are common contributing factor to crashes. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. OR 140 from Plush Cutoff Road to Plush-Adel Road observed data. Road winds through canyon. Fort Rock Road to Christmas Valley "S" turns. Traffic speed through Christmas Valley "S" turns. Safety Christmas Valley "S" turns. Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Steep grade east of Christmas Valley. Currently posted at 8%. OR 140 ~10 miles west of Nevada border Safety Oil Dri Road (5-14G) Active Sidewalks to Paisley School Transportation Limited sidewalks exist Limited recreational biking routes exist. Potential	Safety	_	
Safety OR 31 along Summer Lake County of fixed-object crashes. Wind and speed are common contributing factor to crashes. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. OR 140 from Plush Cutoff Road to Plush-Adel Road Observed data. Road winds through canyon. Fort Rock Road to Christmas Valley "S" turns. County officials and residents believe these turns have a high potential for crashes. Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Safety Christmas Valley Road at 8%. OR 140 ~10 miles west of Nevada border Safety Oil Dri Road (5-14G) Active Sidewalks to Paisley School Transportation in Paisley High frequency of fixed-object crashes. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. High frequency of fixed-object crashes. County officials and residents believe these turns have a high potential for crashes. Seigenty Sidewalks to Paisley School in Paisley Limited sidewalks exist Limited recreational biking routes exist. Potential		OR 31 from Deschutes	High frequency of crashes, particularly animal and fixed
Safety OR 31 along Summer Lake are common contributing factor to crashes. County officials and area residents believe a warning device may be needed to alert drivers to this intersection. OR 140 from Plush Cutoff Road to Plush-Adel Road observed data. Road winds through canyon. Fort Rock Road to Christmas Valley "S" turns. County officials and residents believe these turns have a high potential for crashes. Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Safety Christmas Valley Road at 8%. OR 140 ~10 miles west of Nevada border Safety Oil Dri Road (5-14G) Active Sidewalks to Paisley School Transportation Active Sidewalks to Paisley School In Paisley Limited sidewalks exist County officials and residents believe these turns have a high potential for crashes. Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Steep grade east of Christmas Valley. Currently posted at 8%. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Limited sidewalks exist Limited recreational biking routes exist. Potential	Safety	County to Fort Rock Road	object crashes. More passing lanes may be needed.
County officials and area residents believe a warning device may be needed to alert drivers to this intersection. OR 140 from Plush Cutoff Road to Plush-Adel Road observed data. Road winds through canyon. Fort Rock Road to Christmas Valley "S" turns. Christmas Valley "S" turns. Safety Christmas Valley "S" turns. Christmas Valley "S" turns. Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Steep grade east of Christmas Valley. Currently posted at 8%. OR 140 ~10 miles west of Safety Oil Dri Road (5-14G) Active Sidewalks to Paisley School Transportation in Paisley County officials and area residents believe a warning device may be needed to alert drivers to this intersection. High frequency of crashes. 2 fatalities over 5 years of observed data. Road winds through canyon. County officials and area residents believe these turns have observed data. Road winds through canyon. County officials and residents 2 fatalities over 5 years of observed data. Road winds through canyon. County officials and residents 2 fatalities over 5 years of observed data. Road winds through canyon. County officials and residents 2 fatalities over 5 years of observed data. Road winds through canyon. County officials and residents 2 fatalities over 5 years of observed data. Road winds through canyon. County officials and residents believe these turns have a high potential for crashes. Steep grade as to for christmas Valley. Currently posted at 8%. Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Limited sidewalks exist Limited recreational biking routes exist. Potential			High frequency of fixed-object crashes. Wind and speed
device may be needed to alert drivers to this intersection. OR 140 from Plush Cutoff Road to Plush-Adel Road Observed data. Road winds through canyon. Fort Rock Road to County officials and residents believe these turns have a high potential for crashes. Traffic speed through Christmas Valley "S" turns. Safety Christmas Valley Road OR 140 ~10 miles west of Safety Oil Dri Road (5-14G) Safety Oil Dri Road (5-14G) Active Transportation CR 140 from Plush Cutoff Intersection. High frequency of crashes. 2 fatalities over 5 years of observed data. Road winds through canyon. County officials and residents believe these turns have a high potential for crashes. Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Steep grade east of Christmas Valley. Currently posted at 8%. OR 140 ~10 miles west of Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Active Sidewalks to Paisley School in Paisley Limited sidewalks exist Limited recreational biking routes exist. Potential	Safety	OR 31 along Summer Lake	-
Safety US 395 / OR 31 intersection. OR 140 from Plush Cutoff Road to Plush-Adel Road observed data. Road winds through canyon. Fort Rock Road to County officials and residents believe these turns have a high potential for crashes. Residents have concerns about high traffic speeds through Christmas Valley Speed was a factor in 6 of 13 reported crashes. Safety Christmas Valley reported crashes. Steep grade east of Christmas Valley. Currently posted at 8%. OR 140 ~10 miles west of Nevada border Safety Oil Dri Road (5-14G) Active Sidewalks to Paisley School Transportation OR 140 from Plush Curtoff High frequency of crashes. 2 fatalities over 5 years of observed data. Road winds through canyon. County officials and residents believe these turns have a high potential for crashes. Sesidents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Steep grade east of Christmas Valley. Currently posted at 8%. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Active Sidewalks to Paisley School in Paisley Limited sidewalks exist Limited recreational biking routes exist. Potential			,
OR 140 from Plush Cutoff Safety Road to Plush-Adel Road Observed data. Road winds through canyon. Fort Rock Road to Christmas Valley "S" turns. County officials and residents believe these turns have a high potential for crashes. Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Safety Christmas Valley Safety Christmas Valley Road Safety OR 140 ~10 miles west of Nevada border Safety Oil Dri Road (5-14G) Active Transportation OR 140 from Plush Cutoff High frequency of crashes. 2 fatalities over 5 years of observed data. Road winds through canyon. County officials and residents believe these turns have a high potential for crashes. Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Steep grade east of Christmas Valley. Currently posted at 8%. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Active Sidewalks to Paisley School Transportation in Paisley Limited sidewalks exist Limited recreational biking routes exist. Potential			•
Safety Road to Plush-Adel Road Fort Rock Road to Safety Christmas Valley "S" turns. Residents have concerns about high traffic speeds through Christmas Valley Traffic speed through Christmas Valley Safety Christmas Valley Steep grade east of Christmas Valley. Currently posted at 8%. OR 140 ~10 miles west of Safety Nevada border Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Active Sidewalks to Paisley School Transportation In Paisley Limited sidewalks exist Limited recreational biking routes exist. Potential	Safety	-	
Fort Rock Road to Christmas Valley "S" turns. Residents have concerns about high traffic speeds through Christmas Valley "S" turns. Safety Christmas Valley reported crashes. Safety Christmas Valley Road Safety Christmas Valley Road at 8%. OR 140 ~10 miles west of Nevada border Safety Oil Dri Road (5-14G) Active Transportation in Paisley Fort Rock Road to County officials and residents believe these turns have a high potential for crashes. Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Steep grade east of Christmas Valley. Currently posted at 8%. Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Limited sidewalks exist Limited recreational biking routes exist. Potential	Cafai		
Safety Christmas Valley "S" turns. a high potential for crashes. Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Safety Christmas Valley Steep grade east of Christmas Valley. Currently posted at 8%. OR 140 ~10 miles west of Safety Nevada border Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Active Sidewalks to Paisley School Transportation in Paisley Limited sidewalks exist Limited recreational biking routes exist. Potential	Safety		
Residents have concerns about high traffic speeds through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Safety Christmas Valley Road safety Christmas Valley Road at 8%. OR 140 ~10 miles west of Nevada border Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Active Sidewalks to Paisley School Transportation in Paisley Limited sidewalks exist Limited recreational biking routes exist. Potential	Cafaty		
Traffic speed through Safety Christmas Valley Safety Christmas Valley Safety Christmas Valley Road Safety Christmas Valley Road Safety Christmas Valley Road OR 140 ~10 miles west of Nevada border Safety Oil Dri Road (5-14G) Active Transportation Traffic speed through Christmas Valley. Speed was a factor in 6 of 13 reported crashes. Steep grade east of Christmas Valley. Currently posted at 8%. Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Limited sidewalks exist Limited recreational biking routes exist. Potential	Salety	Christmas valley 3 turns.	• ,
Safety Christmas Valley Safety Christmas Valley Road Safety Christmas Valley Road OR 140 ~10 miles west of Safety Nevada border Safety Oil Dri Road (5-14G) Active Transportation Transportation Christmas Valley Road At 8%. Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Limited sidewalks exist Limited recreational biking routes exist. Potential		Traffic speed through	
Safety Christmas Valley Road OR 140 ~10 miles west of Safety Nevada border Safety Oil Dri Road (5-14G) Active Transportation Transportation Steep grade east of Christmas Valley. Currently posted at 8%. Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Limited sidewalks exist Limited recreational biking routes exist. Potential	Safety		
Safety Christmas Valley Road OR 140 ~10 miles west of Safety Nevada border Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Active Transportation Transportation Christmas Valley from the south. Blowing dust and sand limits visibility. Limited sidewalks exist Limited recreational biking routes exist. Potential	Surety	emistrius vancy	·
OR 140 ~10 miles west of Safety Nevada border Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Active Transportation OR 140 ~10 miles west of Steep grade on the highway. Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Limited sidewalks exist Limited recreational biking routes exist. Potential	Safety	Christmas Valley Road	
Safety Oil Dri Road (5-14G) Main route to Christmas Valley from the south. Blowing dust and sand limits visibility. Active Sidewalks to Paisley School Transportation in Paisley Limited sidewalks exist Limited recreational biking routes exist. Potential	,	<u> </u>	
Safety Oil Dri Road (5-14G) dust and sand limits visibility. Active Sidewalks to Paisley School In Paisley Limited sidewalks exist Limited recreational biking routes exist. Potential	Safety	Nevada border	Steep grade on the highway.
Active Sidewalks to Paisley School Transportation in Paisley Limited sidewalks exist Limited recreational biking routes exist. Potential			Main route to Christmas Valley from the south. Blowing
Transportation in Paisley Limited sidewalks exist Limited recreational biking routes exist. Potential	Safety	Oil Dri Road (5-14G)	dust and sand limits visibility.
Limited recreational biking routes exist. Potential		-	
	Transportation	in Paisley	
1			
Active locations may include county roads around Lakeview			
Transportation Recreational biking routes and the City of Paisley.	Transportation	Recreational biking routes	
		History 424 (OD 440)	Review bridge characteristics to determine contributing
	Dridge		factors to low sufficiency rating and determine whether
Bridge Bridge 08848A repair or upgrade is needed.	Briage		Review bridge characteristics to determine contributing
			factors to low sufficiency rating and determine whether
Bridge 08850 repair or upgrade is needed.	Bridge		, -
	2/1480		Review bridge characteristics to determine contributing
			factors to low sufficiency rating and determine whether
Bridge 08849 repair or upgrade is needed.	Bridge		

Kittelson & Associates, Inc.

Bend, Oregon

Category	Name	Description
Bridge	Highway 431 (OR 140), Bridge 09538	Review bridge characteristics to determine contributing factors to low sufficiency rating and determine whether repair or upgrade is needed.
Maintenance	County system	Lake County struggles to maintain roadways to acceptable standard. Ongoing maintenance funding is challenging.
Roadway/Freight Route	OR 31	OR 31 is not currently designated as a truck route. Designating this road as such may increase economic opportunities for the County.
Roadway/Freight Route	OR 140 east of Lakeview	OR 140 currently has length restrictions that limit freight movement on this route. Removing this length restriction is a priority for the County.
Recreation	Signage	The county needs to prioritize signage to recreational areas to boost economic opportunities that could result from tourism, etc.

NEXT STEPS

Future alternatives will be developed based on the needs identified in this memorandum. These alternatives will be presented to the Project Advisory Committee and public during scheduled meetings in October 2015.

Kittelson & Associates, Inc.

Bend, Oregon